


SC-1000 Cutting Template



Bezel Footprint

Drilling/Cutting Lines

When printing this file DO NOT scale image up or down in size. This will cause the drilling locations to be misaligned to the product.